From: Nicholas Steenhaut

To: Geiger, William; Travis.T.Fatzinger@usace.army.mil
Cc: Joseph Vitale; Walter J. Papp, Jr. (walter@racllc.com)

Subject: FW: Update

Date: Tuesday, January 12, 2016 12:27:47 PM

Attachments: image001.png

12C1135 Metal Bank Calc Package 2016-01-11.pdf 12C1135 Metal Bank Repair 01-07-2016.pdf

Will, Travis,

Please find the supporting calculations attached for the proposed waler design changes previously communicated to you with our response to comments on December 24, 2015. In addition to the supporting calculations attached hereto, we are also providing an updated set of drawings for your records. Please note that there is a small change from the version of Figure 3 included with our response to comment letter, namely, a cap plate that was depicted on a detail drawing has been removed since it is not part of the planned repairs.

If you have any questions or require any clarification, don't hesitate to contact me. Sincerely,

Nicholas Steenhaut

Senior Manager D +1 617 9466109 M +1 607 2620139

NSteenhaut@environcorp.com

Ramboll Environ 20 Custom House Street Suite 800 Boston, MA 02110

www.ramboll-environ.com



This message contains information that may be confidential, privileged or otherwise protected by law from disclosure. It is intended for the exclusive use of the Addressee(s). Unless you are the addressee or authorized agent of the addressee, you may not review, copy, distribute or disclose to anyone the message or any information contained within. If you have received this message in error, please contact the sender by electronic reply to email@ramboll.com and immediately delete all copies of the message.